

Job # IH21-057
 Name of Building: Administration Building
 Address: 809 Hecla, Hancock MI

Copper Country ISD
 Reinspection Form

DeLisle Associates
 Date: 8/2/2021

FUN_DESC	FUN_NUM	T,S,M	SF	LF	MAT_DESC	DAM	Reason For Change	RA	SAM #	Y,N,A
BOILER (ROOM 112)	001	M	20	0	FIRE DOOR	L	Continue O and M	1		A
TUNNEL	002	T	0	20	WOOLFELT JTS	L	Continue O and M	1		Y
TUNNEL	002	T	0	400	WOOLFELT	L	Continue O and M	1		Y
MULTI PURPOSE (ROOM 105)	003	M	1512	0	9" X 9" FT	L	Removed 288 July 2021	1		Y
MULTI PURPOSE (ROOM 105)	003	T	0	60	MAG PIPE	L	Continue O and M	1		Y
KITCHEN (ROOM 111)	004	M	800	0	9" X 9" FT	L	Continue O and M	1		Y
KITCHEN (ROOM 111)	004	T	0	40	MAG PIPE	L	Continue O and M	1		Y
BLRM/CAFE HALL	005	M	150	0	9" X 9" FT	L	Continue O and M	1		Y
BLRM/CAFE HALL	005	M	20	0	FIRE DOOR	L	Continue O and M	1		A
BSMT OFFICES	006	T	0	400	WOOLFELT	L	Continue O and M	1		Y
BSMT OFFICES	006	T	0	600	MAG PIPE	L	Continue O and M	1		Y
BSMT OFFICES	006	M	400	0	9" X 9" FT C/O	L	Continue O and M	1		Y
BSMT OFFICES	006	T	0	200	AIRCELL	L	Continue O and M	1		Y
BASEMENT HALL	007	M	50	0	9" X 9" FT	L	Continue O and M	1		Y
BSMT CONFERENCE RM	008	M	50	0	9" X 9" FT	L	Continue O and M	1		Y
ROOM 108	009	M	150	0	9" X 9" FT C/O		Removed July 2021			Y
ROOM 108	009	T	0	25	MAG PIPE	L	Continue O and M	1		Y
ROOM 107	010	M	150	0	9" X 9" FT C/O		Removed July 2021			Y
ROOM 107	010	T	0	25	MAG PIPE	L	Continue O and M	1		Y
ROOM 109	012	M	100	0	9" X 9" FT	L	Removed 50 SF July 2021	1		Y
ROOM 109	012	T	0	70	MAG PIPE	L	Continue O and M	1		Y
ROOM 110	013	M	100	0	9 X 9 FT C/O	L	Removed 50 SF July 2021	1		Y
ROOM 110	013	T	0	25	MAG PIPE	L	Continue O and M	1		Y
CLASSROOM HALLWAY	014	M	2500	0	9" X 9" FT		Removed July 2021			Y
CLASSROOM HALLWAY	014	T	0	150	MAG PIPE	L	Continue O and M	1		Y
ROOM 106	015	M	100	0	9" X 9" FT C/O		Removed July 2021			Y
ROOM 106	015	T	0	30	MAG PIPE	L	Continue O and M	1		Y
MENS RR	017	T	0	25	MAG PIPE	L	Continue O and M	1		Y
MENS RR	017	T	0	1	WOOLFELT	L	Continue O and M	1		Y
WOMENS RR	018	T	0	25	WOOLFELT	L	Continue O and M	1		Y
ROOM 101	019	M	900	0	9" X 9" FT C/O		Removed July 2021			Y
ROOM 102	020	T	0	35	MAG PIPE	L	Continue O and M	1		Y
ROOM 102	020	M	60	0	9" X 9" FT C/O	L	Removed 840 SF July 2021	1		Y
RM 114 (LEARNING CNTR OFF)	022	M	400	0	9" X 9" FT C/O	L	Continue O and M	1		Y
ROOM 118	024	M	10	0	9" X 9" FT C/O	L	Carpeted Over	1		Y

(RA) Response Action

- 1) Operations and Maintenance 2) Repair
 3) Encasement 4) Encapsulate 5) Removal

Job # IH21-057
 Name of Building: Administration Building
 Address: 809 Hecla, Hancock MI

Copper Country ISD
 Reinspection Form

DeLisle Associates
 Date: 8/2/2021

<i>FUN_DESC</i>	<i>FUN_NUM</i>	<i>T,S,M</i>	<i>SF</i>	<i>LF</i>	<i>MAT_DESC</i>	<i>DAM</i>	<i>Reason For Change</i>	<i>RA</i>	<i>SAM #</i>	<i>Y,N,A</i>
ROOM 119 PRINCIPAL'S OFFICE	027	M	100	0	9" X 9" FT C/O	L	Continue O and M	1		Y
ROOM 119 OUTER OFFICE	029	M	250	0	9" X 9" FT C/O	L	Continue O and M	1		Y
Room 120 and 122	030	M	200	0	9" X 9" FT C/O	L	Carpeted Over	1		Y
ROOM 121	032	M	10	0	9" X 9" FT C/O	L	Continue O and M	1		Y
ROOM 125	033	M	10	0	9" X 9" FT C/O	L	Continue O and M	1		Y
LOBBY	035	M	30	0	9" X 9" FT	L	Continue O and M	1		Y
SW STORAGE AREA BSMT	047	T	0	130	WOOLFELT	L	Continue O and M	1		Y
OFFICE HALLWAY	042	M	800	0	9" X 9" FT C/O	L	Continue O and M	1		Y

(RA) Response Action

- 1) Operations and Maintenance
- 2) Repair
- 3) Encasement
- 4) Encapsulate
- 5) Removal